
CITY OF BALTIMORE WET W SMOKE AND DYED W	Page <u>l</u> of <u>6</u>	
Sewershed: PATAPSCO	Company: Savin Engineers	Date: /٥٠6 '०१
Test to be Performed:	Ground Condition:	Supervisor: Joe Mirabito
Smoke: X Dyed Water:	Dry: X Damp: Wet:	
Manhole ID: <u>\$3301 \ 018 mH.</u>	Test ID: <u>\$ /0 41 - / 3/</u>	Notifications Made: <u>X</u> (Residents, Fire, 311)



CITY OF BALTIMORE WET WEATHE SMOKE AND DYED WATER						Page <u>2</u> of <u>6</u>				
Sewer	vershed: PATAPSCO			Company: <u>SAVIN</u>				Date: <u>10/6/09</u>		
Test to	be Performed:			Ground	Ground Condition:				Supervisor:JAM	
Smoke	e: <u>X</u> Dy	ed Water:		Dry: <u>X</u>	Dam	p: Wet	::			
Manhol	le ID:S33	<u>01_018MH</u>		Test ID: <u>\$1041-131</u>			Notifications Made: X (Residents, Fire, 311)			
	Sketch: (Showons, Street Nam						•			
Defect				Source		_	Drainage	_	Photo	
No.		Address		Туре	Location		Area	Severity	Number	
1	3062 ASCE	ENSION ST.		3	7	2	0	3	P01	
0								_		
2	3055 ASC	ENSION ST		3	7	2	0	4	P01	
3	500 SEAGU	 ΤΤ.Τ. Δ\/F		3	7	2	0	4	P01	
3	JOO BEAGO	JEE AVE.			,		Ŭ	-	101	
4	510 SEAGU	JLL AVE.		3	7	2	10	4	P01	
5	515 SEAG	ULL AVE.		3	7	2	0	4	P01	
6	507 SEAG			3	7	2	0	4	P01	
U		ULLI AVE.		ی	,	۷	0	7	FUI	
7	501 SEAG	ULL AVE.		3	7	2	0	4	P01	
	<u> </u>									
	 									
	<u></u>									
				OBSERV	/ATION	CODES				
	Source Type	Location	Sector	Severity		Source Type	Location			
01	Main Sewer	Paved Concrete	Public	No Smoke	10		Non-Paved			
02	Service Line	Paved Asphalt	Private	Trace	11	Storm Drain	Field/Woods			
03	Cleanout	Paved Other		Moderate		Catch Basin/Inlet	· ·			
	Downspout	Driveway		Major			Golf Course			
	Area Drain	Sidewalk					Other			
	Driveway Drain	Curb Yard- Front				Excavation				
	Stairwell Drain Foundation Drain	Yard- Front Yard-Back			16	Other				
	Building Interior	Yard- Side								

CITY OF BALTIMORE WET W SMOKE AND DYED W	Page <u>3</u> of <u>6</u>	
Sewershed: PATAPSCO Company: Savin Engineers		Date: <u>10/6/09</u>
Test to be Performed:	Ground Condition:	Supervisor: Joe Mirabito
Smoke: X Dyed Water:	Dry: X Damp: Wet:	
Manhole ID: S3301_018MH	Test ID: <u>\$1041-131</u>	Notifications Made: X (Residents, Fire, 311)



S1041-131-0B1-P01



S1041-131-OB02-P01

CITY OF BALTIMORE WET W SMOKE AND DYED W	Page <u>4</u> of <u>6</u>	
Sewershed: PATAPSCO	ATAPSCO Company: Savin Engineers	
Test to be Performed:	Ground Condition:	Supervisor: Joe Mirabito
Smoke: X Dyed Water:	Dry: X Damp: Wet:	
Manhole ID: <u>\$3301_018MH</u>	Test ID: <u>\$1041-131</u>	Notifications Made:_X_ (Residents, Fire, 311)



S1041-131-OB03-P01



S1041-131-OB04-P01

CITY OF BALTIMORE WET W SMOKE AND DYED W	Page <u>5</u> of <u>6</u>	
Sewershed: PATAPSCO	Company: Savin Engineers	Date: <u>10/6/09</u>
Test to be Performed:	Ground Condition:	Supervisor: Joe Mirabito
Smoke: X Dyed Water:	Dry: X Damp: Wet:	
Manhole ID: <u>\$3301_018MH</u>	Test ID:S1041-131	Notifications Made:_X_ (Residents, Fire, 311)



S1041-131-OB05-P01



S1041-131-OB06-P01

CITY OF BALTIMORE WET W SMOKE AND DYED W	Page <u>6</u> of <u>6</u>	
Sewershed: PATAPSCO	Date: <u>10/6/09</u>	
Test to be Performed:	Ground Condition:	Supervisor: Joe Mirabito
Smoke: X Dyed Water:	Dry: X Damp: Wet:	
Manhole ID: <u>S3301_018MH</u>	Test ID:S1041-131	Notifications Made: X (Residents, Fire, 311)



S1041-131-OB07-P01